

For Cryolabs and Cryostors.



The following is included:

● HIDE GLOVES

Better grip on cold valves.

● WARNING SIGNS

For inside and outside laboratory

● CRYO-APRON

protects body against spills.

● FACE MASK

protects eyes against LN2 splashes

When ordering
request PACK 1.

It is advisable to wear cryogenic gloves, face mask and apron when dispensing liquid nitrogen. If there are a lot of vessels to fill it may well be advisable to also include an Oxygen alarm. as well.

For larger Cryostors and sample handling.



The following is included:

- **HIDE GLOVES**
For handling cold hoses and valves.
- **CRYO-APRON**
protects body against spills.
- **PERSONAL O2 ALARM**
User protection.
- **WARNING SIGNS**
For inside and outside laboratory
- **FACE MASK**
protects eyes against LN2 splashes
- **CRYOGLOVES**
For sample extraction..

When ordering
request PACK 2.

It is advisable to wear cryogenic gloves, face mask and apron when dispensing liquid nitrogen. If there are a lot of vessels to fill it may well be advisable to also include an Oxygen alarm. as well.

The following part numbers are included in this system:
9701110 (1) (2) - 8701032 - 8701031 - 3800150 - 9701113 (5) (7) (9) - 9702141

For cryogenic storage rooms..



The following is included:

- **WALL MOUNTED O2 ALARM**
With %O2 display and beacon/sounder.
- **FACE MASK**
protects eyes against LN2 splashes
- **PERSONAL O2 ALARM**
User protection.
- **WARNING SIGNS**
For inside and outside laboratory
- **CRYO-APRON**
protects body against spills.
- **CRYOGLOVES**
For sample extraction..
- **HIDE GLOVES**
For handling cold hoses and valves.

When ordering
request PACK 3.

It is advisable to wear cryogenic gloves, face mask and apron when dispensing liquid nitrogen.
If there are a lot of vessels to fill it may well be advisable to also include an Oxygen alarm as well.

The following part numbers are included in this system:

9701110 (1) (2) - 8701032 - 8701031 - 3800150 - 9701113 (5) (7) (9) - 9702141 - 9702256